


COS2010 MANUAL ADDENDUM

This addendum applies only to units manufactured after March 25, 2002.

This version of the COS2010 supports a 3 wire interface. This means that the CO interconnect line and the smoke alarm (SA) interconnect line may be connected together and interconnected with compatible CO and smoke alarms. COS2010 units manufactured prior to March 25, **DO NOT** support this form of interconnection of the CO and smoke functions.

3 Wire Interconnection



Alternatively, the interconnect lines may be left unconnected and the alarm will continue to support a 4 wire configuration. In a 4 wire configuration, COS2010 combination alarms are connected to each other using a separate conductor for each of the CO and the smoke alarm (SA) interconnect lines. In this configuration, units manufactured prior to March 25, may be connected to units manufactured after March 25, 2002.

4 Wire Interconnection

